

VEHICLE INSPECTION REPORT

284530

KUBOTA K008-3

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	Fuel Type	DIESEL	Body Style	MINI EXCAVATOR
Year	Colour		Gearbox	HYDROSTATIC
Mileage	1,122 Hours Warranted	VIN		

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



